Rosemary Inn, Cara Mia Cabin (Bldg. No. 382) Olympic National Park Barnes Point, Lake Crescent Port Angeles Vicinity Clallam County Washington HABS No. WA-185-J

WASH
5-POAN.V,

PHOTOGRAPHS


WRITTEN HISTORICAL AND DESCRIPTIVE DATA

Historic American Building Survey
National Park Service
Western Region
Department of the Interior
San Francisco, California 94107

NATIONAL PARK SERVICE Department of the Interior

HISTORIC AMERICAN BUILDING SURVEY ARCHITECTURAL DATA FORM

STATE	COUNTY	TOWN OR VICINITY Approximately 20 miles southwest of	
WASHINGTON	CLALLAM Port An		
HISTORIC NAME OF STRUCTURE (in	clude source for name)	HABS NO.
Rosemary Inn, "Cara Mia" Cabin		WA-185-J	
SECONDARY OR COMMON NAMES OF STRUCTURE			
Bldg. No. 382			
COMPLETE ADDRESS (for rural sites describe location) Barnes Point, south shore of Lake Crescent, north side of Hwy 101, approximately 20 miles from Port Angeles, in Olympic National Park.			
DATE OF CONSTRUCTION (include source) Early to mid-1920s (Historic Building Inventory) ARCHITECT(S) (include source) Builder and Craftsman: John Daum (HRS, 1983)			
SIGNIFICANCE (architectural and historical, include original use of structure) This cabin was constructed as an integral part of the Rosemary Inn Complex. It contributes to the overall character of the rustic, picturesque resort ensemble and possesses integrity of design, materials, workmanship, location, setting, feeling and association.			
STYLE (if appropriate)			
Craftsman-style cottage			
MATERIAL OF CONSTRUCTION (include structural systems)			
Wood-frame construction set on 6×6 posts on concrete piers; concrete blocks under porch.			
SHAPE AND DIMENSIONS OF STRUCTURE (sketched floor plans on separate sheet acceptable) Rectangle: 12' x 16' with a 4' x 6' extension on east.			
EXTERIOR FEATURES OF NOTE -story; wood-shingled gable roof with extended eaves, knee braces and exposed rafter ends; shed-roofed entry overhang on west supported by curved knee braces; vertical board and batten siding with wood shingle above; multi-paned hinged sash with plain trim; entry porch has open "stickwork" screening set on vertical board and batten boxed rails; plain corner and fascia boards.			
INTERIOR FEATURES OF NOTE (describe floor plans if not sketched)			
Painted floor boards; vertical board wainscotting on walls.			
		•	
MAJOR ALTERATIONS AND ADDITIONS, WITH DATES			
PRESENT CONDITION AND USE			
Fair; Vacant			
OTHER INFORMATION AS APPROPRIATE			
SOURCES OF INFORMATION (include listing on National Register, State Registers, etc.) Historic Structure Report, 1986 Historic Resource Study, 1983 Historic Building Inventory, 1983			
COMPILER, AFFILIATION			DATE
Gretchen A. Luxenberg, Nationa	I Park Service		July, 1988





Cara Mia Building #382